

Fuel labels are made from

LABELS	
GLL10	"Gasoline Only" Label (Red)
GLL20	"Diesel Fuel Only" Label (Yellow)
GLL23	SS Pro Burner Control Label 11" x 3" Label
GLL24	Label HN English/French Warnings (3.5 x 2)
GLL26	"Caution: Keep Hands Out" Label (4.5 x 3)
GLL27	"Caution: Auto Start/Stop" Label (4.5 x 3)
GLL28	Label ETL Certification
GLL29	"Burner On/Off" Safety Label (4 x 3)
GLL30	Maintenance Label (3.75 x 3.75)
GLL35	Trailer Valve Label (5 x 1.75)
GLL36	Hydro Tek Promotional Triangle Logo Label (13.5 x 25)
GLL37	Hydro Tek Triangle Logo Label 10" x 19" for Tanks
GLL40	Label, Model #
GLL45	HP Series Label (Pre-HX Series) HP Series Only
GLL46	HX Machine Panel Label 3.5" x 34.5"
GLL47	HP/ HX Machine Box Label 9" x 7"
GLL51	SC Machine Operation Label (13 x 2.5) Pre. '99
01150	(Must Also Purchase GLL52)
GLL52	SC Machine Warning/Control Label (8 x 7.5) Pre. '99
GLL53	(Must Also Purchase GLL51) SC Machine Operation/Warning Label 4" x 31"
GLL53 GLL54	Label SC Variable Flow Instructions (10.75 x 3)
GLL54 GLL57	SS/SC Machine Panel Control Box Label (7.25 x 3.75)
GLL58	SS Machine Operation/Warning Label 4" x 29"
GLL60	CP Series Label (16 x 1.75)
GLL63	CW Series Remote Label 5" x 6"
GLL64	CW Machine Label 5" x 5"
GLL66	Hydro Twister label 11" x 8"
GLL67	CPK HydroPro Series Base Label (10.5 x 2.5)
GLL68	Label, Central Wash Remote
GLL69	SM Machine Control Panel Label (3.5 x 39.5)
GLL75	Hydro Tek Logo Label (2.75 x 34)
GLL76	Hot-2-Go Hydro Tek Label (3.5 x 15.25)
GLL77	HG Instruction / Control Box Label (2 Piece Label)
	Box-3.75 x 7.5; Panel-3.75 x 8.5
GLL80	Hydro Tek Logo Label 6" x 37"
GLL91	HN/CN Series Pump Control Label (9 x 7)
GLL92	HN Series Burner Control Label (9.5 x 7.5)
GLL93	HN Pro Series Control Box Cover Label (9.5 x 7.5)
GLL95	Pro Line Series Label with Instructions (3 x 21)


Hydro Tek Instruction and safety labels have a clear mylar overlay over the type to ensure they remain easy to read

GLL36 Customize with your phone number.











GLL29



GLL75





Installation Instructions:

- 1. For clear labels pre-mix water with 3 drops of liquid detergent in a spray bottle.
- Clean smooth or stainless surfaces with alcohol or equivalent that 2. evaporates quickly. Prepare powder coated surfaces with "Scotch Bright" abrasive pad or equivalent. Wipe with lint free cloth using alcohol or equivalent.
- 3. Spray surface and back of label with water solution. Labels applied to powder coated surfaces do not use water soulution.
- 4. Place label and align.
- 5. Spray front of label with water solution and use a squee-gee to smooth out bubbles and water, working from the center out.
- 6. Dab dry with towel and allow additional time to sit and dry.
- www.etspressurewashers.com

Toll Free (7:30-4:00 EST) Phone (877) 824-7763 Fax (610) 583-5479